




# MINOS Status Report



Steve Hahn



- This week
  - Live time: 99.6%
  - POT fraction: 99.8%
- Wednesday ND coil tripped off while MI HV101 dipole string which had overheated was being repaired/cleaned
  - Brought back online quickly
  - Discussion with Walt Jaskierny; probably needs day-long downtime for maintenance
- Electronics spare work:
  - 6 repaired Minders from Argonne
  - 2 Masters and 2 Minders taken for repair to Argonne
  - Determining spares/testing for rarer cards: Keepers, Master Clock cards
  - Work continues on Minder and Master crate power supplies



# MINOS Status Report

Steve Hahn



- This week
  - Live time: 99.8%
  - POT fraction: 99.4%
- No outstanding problems (O.K., noisy fluorescent tube)