

	Initial Phase	Commissioning Phase	Routine Phase
Pre-checked	Minimal checkout facilities needed. Assumed good, check for shipping damage, perhaps powerup.	Extensive checkout facilities needed. Possibility of comprehensive debugging.	Minimal checkout facilities needed. Assumed good, failures sent back for repair
Commercial	Burn-in, functional checkout facilities needed. Failures sent back to manufacturer	Burn-in, functional checkout facilities needed. Failures sent back to manufacturer	Burn-in, functional checkout facilities needed. Failures sent back to manufacturer
Used	Need to test functionality and minor diagnostic capability.	Need to test functionality and minor diagnostic capability.	Need to test functionality and minor diagnostic capability.