



# NuMI-MINOS Status Report - Nick Graf



## NEAR DETECTOR




### Other issues

- Fan warnings may become a bigger problem later. Help from CDF technicians in repairing spare packs.
- Hall temperature increasing. Air handler unit awaiting repairs.

Near Detector: Monday May 2 - Sunday May 8

- Live Time: 71.8% good physics data.
- POT fraction: 52.4% good physics data.
- DAQ issues
  - 1 of 4 branches stopped responding Tuesday night and would not initialize.
  - Suspected card in back end electronics crate.
  - Down much of the day on Wednesday.
  - Resumed running late afternoon without this branch. DAQ crashed again that night.
  - Thursday fixed first problem by swapping a card in branch PC. Second problem required swap of read out processor (ROP) board.
  - Frequent ROP failures in this crate. Investigating possible causes.

# NuMI-MINOS Status Report - Nick Graf



## FAR DETECTOR



## Soudan: Last week

- Live Time: 99.9% good physics data.
- POT Fraction: 99.8% good physics data.
- FD has been running well.
- A few minor problems to be addressed while NT02 is installed.